



Spannungen sind gemessen mit Multimeter (3300V) im 30V- bzw. 600V-Bereich gegen Masse bei 220V Messgeschl. AM (MW) FM (UKW)

Pos. 1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33
R	50K	70	1M	200K	50K	30	50K	2K	100K	50K	2M	50K	100K	100K	100K	100K	100K	100K	100K	100K	100K	100K	100K	100K	100K	100K	100K	100K	100K	100K	100K	100K
C	50	500	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000	1000
Pos. 34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	
C	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	100	



WEGA FOX 56

Type: 1085
WEGA RADIO
Stuttgart

Schalter in Arbeitsstellung gezeichnet
I II III IV V
Aus TA MW UKW